


Item	Defect Code	Demerit Class	Description of Defects	Localisation <small>Interior, underframe, roof etc</small>	End <small>(1) or (2)</small>	Side <small>Left [L] or Right [R]</small>	Action Required <small>(Ready to fix/Part needed/ NCR/ Work instruction required for special process rework)</small>	Quality Sign-off	Prasa Sign-off
1			Sparkers on side sill (1.4kg pad)	1150 VF		L			
									

This document and the information contemplated therein have to be considered as Confidential information pursuant to the provisions of Clause 25 of the MoA, and treated as such.

Train #	219	Car #	M3	TC1	M1	M2	<input checked="" type="checkbox"/> M3	M4	Process Stage	Inspector	Sydney Ben KORNO	Date	26/03/2017	Page	OF
---------	-----	-------	----	-----	----	----	--	----	---------------	-----------	---------------------	------	------------	------	----

Item	Defect Code	Dement Class	Description of Defects	Localisation Interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed/ NCR/ Work instruction required for special process rework)	Quality Sign-off	Prasa Sign-off
1			Sealant gap (rust) on sill 1		1				
2			Mastic not applied						

GIBBELG		GIB000000380	Rev A0	Defects Report	29/03/2017	4/5 Pages
---------	--	--------------	--------	----------------	------------	-----------

This document and the information contained therein have to be considered as Confidential information pursuant to the provisions of Clause 25 of the M&A, and treated as such

