

Train #	Car #	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	Date	Page	of					
21	M2								Nik/Snellby	16/04/21							
Item	Defect Code	Demerit Class	Description of Defects					Localisation	End	Side	Action Required	Quality	Prasa				
			paint touch VPS					Interior, underframe, roof etc	[1] or [2]	Left [L] or Right [R]	(Ready to fix/Part needed/ NCR/ Work Instruction required for special process rework)	Sign-off	Sign-off				

The document and the information contained therein shall be considered as Confidential information pursuant to the provisions of clause 25 of the ACR, and treated as such.

Train #	221	Car #	Tc2	Tc1	M1	M2	M3	M4	Tc2	Process Stage	Inspector	Date	Page				
Item	Defect Code	Demerit Class	Description of Defects								Localisation	End	Side	Action Required	Quality	Prasa	
											Inspection, underframe, roof etc	[1] or [2]	Left [L] or Right [R]	(ready to fix/part needed/ NCR/ Work instruction required for special process, rework)	Sign-off	Sign-off	
1			- Spatter under paint side 2								U/F						
			- U/F														
2			Sealant gap on U/F (damaged)								U/F						
3			paint finish up on latching pad														
Large diagonal scribble covering the main table area																	

GIBBIC

GIB000000380

Rev A0

Defects Report

29/03/2017

4/5 Pages

This document and the information contained therein have to be considered as Confidential information pursuant to the provisions of Clause 20 of the M&A and treated as such.

Train #	221	Car #	M3	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	NTL/Naledi	Date	16/04/24	Page	of
Item	Defect Code	Demerit Class	Description of Defects								Localisation	End	Side	Action Required	Quality	Prasa
			Rust on Insulated Welds End 2								Interior, underframe, roof etc	[1] or [2]	Left [L] or Right [R]	(Ready to fix/Part needed/ NCR/ Work instruction required for special process rework.)	Sign-off	Sign-off