

Train #	228	Car #	TC1	TC	M1	M2	M3	M4	TC2	Process Stage	PC02	Inspector	Arno + Molepodi	Date	22/05/2017	Page	OF									
Item	Defect Code	Demerit Class	Description of Defects									Localisation Interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/part needed/ NCR/ Work instruction required for special process rework)	Quality Sign-off	Prasa Sign-off									
1	C		Touch up painting on EUF1 (General) - CB1D7D									EUF1 + 2	1 + 2	L + R												
2	C		Rust on EUF2 (Grashbox area - from supplier)									EUF2	2	LFR												



GIB0000000380

Rev A0

Defects Report

29/03/2017
4/5 Pages

This document and the information contained therein have to be considered as Confidential Information pursuant to the provisions of Clause 25 of the M&A, and treated as such.

