Train #	284	TS #	EM 01 20 284	TC1	M4	M1	M2	M3	TC2	Process Stage	PC10	Inspector	PRASA and Gibela	Date	6/11/2025	Page	1 of 1

Item		Demerit Class	Defect Description	Localisation Interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed/ NCR/ Work instruction required for special process rework)	Dep Pme,Ops, Warehouse,Design,SQA	GIBELA Sign-off	PRASA Sign-off
Quality Declarations										
1		C	TC1 &M4 fairing cover has stain	INT	1&2	L&R	NCR	CBS		
2		C	M1 R/H lateral display glass is scratched	INT	1&2	L&R	NCR	OPS		
Functional Declaration										
1		B	M3 When doing PEA pull tests the footage does not show	INT	1+2		RTF	T&C		
Engineering defects										
1		C	1/4 window screws discoloration	EXT	1+2	L+R	As Per DPM Discussion	ENG		
2		C	GENERAL : Upper panel above windows are loose	INT	1+2	L+R	As Per DPM Discussion	ENG		
3		C	TC1 Above window 2 ceiling light cover not aligned	INT	1	L	As Per DPM Discussion	ENG		
4		C	TC1 and TC2 LV1 and LV 2 Cubicles are not fixed		1	L+R	As Per DPM Discussion	ENG		
5		C	TC1 Cab ceiling not aligned with windscreen serigraph	INT	1	L+2	Under Investigation	ENG		
Quality Defects										
1		C	GENERAL:Chemical marks on Carbody shell	EXT	1+2	L+R	RTF	FT1041		
Date			9/11/2023							