

| Train # | Car # | TC1 | M1 | M2 | M3 | M4 | Process Stage | Inspector | Date | Page | | | |
|---------|-------------|--------------|-------------------------------------|----|----|----|---------------|-----------------|----------|------|-----------------|------------------|----------------|
| 037 | M4 | | | | | | T | NTK [Signature] | 08/07/24 | 4/5 | | | |
| Item | Defect Code | Dement Class | Description of Defects | | | | | Localisation | End | Side | Action Required | Quality Sign-off | Prasa Sign-off |
| | | | Declaration | | | | | | | | | | |
| | | | - New plates | | | | | | | | | | |
| | | | - plates on end 1 | | | | | | | | | | |
| | | | Paint forced up in underlens bucket | | | | | | 2 | UHL | | [Signature] | [Signature] |
| | | | | | | | | | | | | | |
| | | | [Signature] | | | | | | | | | | |
| | | | [Signature] | | | | | | | | | | |



GIB0000000380

Rev A0

Defects Report

29/03/2017
4/5 Pages

This document and the information contained therein have to be considered as confidential information pursuant to the provisions of Clause 25 of the MOA and treated as such

