


Train #	Car #	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	Date	Page		
M2L	M14					<input checked="" type="checkbox"/>			NW / Nadehi	15/04/24	4/5		
Item	Defect Code	Demerit Class	Description of Defects					Localisation	End	Side	Action Required	Quality Sign-off	Prasa Sign-off
			paint touch up. - lifting pads					head, underframe, roof etc.	[1] or [2]	Left [L] or Right [R]	(Ready to fix/Part needed/ NCV Work instruction required for special process rework)		
<i>[Large diagonal scribble]</i>													
<i>[Handwritten signature]</i>													

The document and the information described therein have to be considered as Confidential information pursuant to the provision of Clause 25 of the NDA, and treated as such.

Train #	Car #	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	Date	Page	OF		
222	M1								NK/Edward	10/27/20				
Item	Defect Code	Dement Class	Description of Defects					Localisation	End	Side	Action Required	Quality	Prasa	
								Inferior, underframe, roof etc	[1] or [2]	Left [L] or Right [R]	Free/ to fix/Part needed/ NCR/ Work Instruction required for special process remark.)	Sign-off	Sign-off	
1			part truck ups on top. 4/ing					CB150						
2			cracking sealant on VI					CB150						
														
 														



GIB000000380

Rev A0

Defects Report

29/03/2017
4/5 Pages

The document and the information contained therein have to be considered as confidential information pursuant to art. 25 of the ICA and revised in 1999

Train #	Car #	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	Date	Page		
202	102						<input checked="" type="checkbox"/>		MTL Nadeki	18/04/24	4/5		
Item	Defect Code	Dement Class	Description of Defects					Localisation	End	Side	Action Required	Quality	Prasa
							Interior, underframe, roof etc	[1] or [2]	Left [L] or Right [R]	(Ready to fix/Part needed/ NCR/ Work instruction required for special process rework)	Sign-off	Sign-off	
1			part touch ups on A1F										
2			Rust on Sealand EUF 2 LHS										
3			Missing Primer EIF 2										

GIBBIC

GIB000000380

Rev A0

Defects Report

29/03/2017
4/5 Pages

Train #	Car #	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	Date	Page	of		
1	TC1								MTC Zealand	18/04/24				
Defect Code	Dement Class	Description of Defects							Localisation <small>Interior, underframe, roof etc</small>	End [1] or [2]	Side Left [L] or Right [R]	Action Required <small>(ready to fix/Part needed/ NCR/ Work Instruction required for special process rework)</small>	Quality Sign-off	Prasa Sign-off
		Paint finish w/5								1/2				
<p>Concern (Sealant from TT1010 not smoothed on WLF)</p> <p><i>[Signature]</i> <i>[Signature]</i></p>														
<p><i>[Large diagonal scribble]</i></p>														

GIBELIO

GIB000000380

Rev A0

Defects Report

29/03/2017
4/5 Pages

This document and the information contained therein are to be considered as Confidential information pursuant to the provisions of Clause 25.5 of the M&A and treated as such