Train #	223	Car #	TC2	TC1	M1	M2	M3	M4	X C2	Process Stage	PCO2	Inspector	Sydney & Lindsay	Date	22/04/24	Page	___ OF ___

Item	Defect Code	Demerit Class	Description of Defects	Localisation Interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed/ NCR/ Work instruction required for special process rework)	Quality Sign-off	Prasa Sign-off
			NO DEFECTS						

GIBELO	GIB0000000380	Rev A0	Defects Report	29/03/2017 4/5 Pages

This document and the information contemplated therein have to be considered as Confidential information pursuant to the provisions of Clause 25 of the MSA, and treated as such

Train #	223	Car #	M3	TC1	M1	M2	X M3	M4	TC2	Process Stage	PLOZ PFAJA	Inspector	Sydney/Thursday	Date		Page	___ OF ___

Item	Defect Code	Demerit Class	Description of Defects	Localisation Interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed/ NCR/ Work instruction required for special process rework)	Quality Sign-off	Prasa Sign-off
			Paint dripping/running on end 1 end UF	UF	1	L&R	CB/220		
			Paint chipped on end UF (generic)	UF	1&2	L&R			
			Sealant detaching on UF near sidewall				CB/070		
			Detaching sealant on UF panels	UF	2		CB/050		

This document and the information contemplated therein have to be considered as Confidential Information pursuant to the provisions of Clause 25 of the MSA, and treated as such

Train #	223	Car #	M1	TC1	X	M2	M3	M4	TC2	Process Stage	PCO2 PRASA	Inspector	Sydney & Lucky	Date	23/04/24	Page	____ OF ____

Item	Defect Code	Demerit Class	Description of Defects	Localisation Interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed/ NCR/ Work instruction required for special process rework)	Quality Sign-off	Prasa Sign-off
			NO Defects						

This document and the information contemplated therein have to be considered as Confidential Information pursuant to the provisions of Clause 25 of the MSA, and treated as such.

Train #	223	Car #	M4	TC1	M1	M2	M3	~~M4~~	TC2	Process Stage	PRASA PCO2	Inspector	Sydney & Lucky	Date	22/04/24	Page	___ OF ___

Item	Defect Code	Demerit Class	Description of Defects	Localisation Interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed/ NCR/ Work instruction required for special process rework)	Quality Sign-off	Prasa Sign-off
			Scratches on end UF (generic) below crash box	UF	1 & 2	L & R	USUNYE		

This document and the information contemplated therein have to be considered as Confidential information pursuant to the provisions of Clause 25 of the MSA, and treated as such

Train #	223	Car #	TC1	TA	M1	M2	M3	M4	TC2	Process Stage	PC02 PRASA	Inspector	Sydney & Lindley	Date	22/07/24	Page	____ OF ____

Item	Defect Code	Demerit Class	Description of Defects	Localisation Interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed/ NCR/ Work Instruction required for special process rework)	Quality Sign-off	Prasa Sign-off
			NO DEFECTS						

This document and the information contemplated therein have to be considered as Confidential Information pursuant to the provisions of Clause 25 of the MSA, and treated as such

Train #	223	Car #	M2	TC1	M1	X M2	M3	M4	TC2	Process Stage	DCO2 PRASA	Inspector	Sydney & Lucky	Date	23/04/24	Page	___ OF ___

Item	Defect Code	Demerit Class	Description of Defects	Localisation interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed/ NCR/ Work instruction required for special process rework)	Quality Sign-off	Prasa Sign-off
			No Defects						

This document and the information contemplated therein have to be considered as Confidential information pursuant to the provisions of Clause 35 of the MCA, and treated as such