



Train #	232	Car #	M <sub>1</sub>	TC1	M1	M2	M3	<input checked="" type="checkbox"/> TC2	Process Stage	PCC2	Inspector	Wardle + AMU	Date	12/06/24	Page	OF
Item	Defect Code	Dement Class	Description of Defects							Localisation <small>(Inator, underframe, roof etc)</small>	End <small>[1] or [2]</small>	Side <small>Left [L] or Right [R]</small>	Action Required <small>(Ready to be Part needed / NCR / Work instructed required for special process follow)</small>	Quality Sign-off	Prasa Sign-off	
			DECLARATION: END 2 SEALANT & IC BOXES							END 2	2	LTR				
1	e	e	Spatter on the side sill (CB1150/CB1330)							Side sill	1	R				
2	e	e	Flash spot on skin (CB1120)							Side wall	1	R				

GIBELG

GIB000000380

Rev A0

Defects Report

29/03/2017  
4/5 Pages

This document and the information contained therein shall be considered as confidential information pursuant to the provisions of Clause 23 of the NCR and treated as such







